

## Deerfield High School Press Box and Concessions

### Area detail:

Concessions	2,565
Press Box	507
<b>Total</b>	<b>3,072</b>
Site (sq. acres)	See Deerfield High School

## District 113 Life Safety items (not from FGM)

Item	Location	Description of Problem	Corrective Measure	notes	code	status	Cost Summary

Life Safety Items Subtotal: \$ -

## Architectural, M,E,P, Building Program and Maintenance Items

Item	Location	Description of Problem	Corrective Measure	Notes	QTY	Unit Cost	Cost Summary
1A	Concessions SB100	Interior CMU wall has visible cracks and/or step cracking.	Remove damaged CMU. Tooth in new CMU and repaint.	SF	3	\$ 200.00	\$ 600.00
19A	Press Box	Acoustic ceiling tile is water stained.	Remove and replace ceiling tile. Investigate source of leak and repair.	SF	10	\$ 15.00	\$ 150.00
32A	Women's Toilet SB101, Men's Toilet SB103	Concrete floor or finish is cracked, has holes, damaged or stained.	Repair surface of concrete flooring and repaint or recoat to match existing.	SF	24	\$ 150.00	\$ 3,600.00
189A	Concessions SB100	Joint between floor and wall is cracked or missing.	Provide sealant at joint.	LF	18	\$ 20.00	\$ 360.00
P1	Custodian SB102	Soap/chemical dispenser does not have separate water supply, ball valve, and RPZ.	Provide separate water supply line, ball valves, check valves and RPZ.		1	\$ 2,000.00	\$ 2,000.00
P2	Mechanical SB104	Water heater cold water supply line is missing a check valve to prevent the pumped return water line from pumping return water back through the cold water supply system.	Provide check valve on the cold water supply line before the pumped hot water return connection to the cold water supply to the water heater.		1	\$ 400.00	\$ 400.00
P3	Concessions SB100	Concession triple compartment sink waste is not connected to a grease trap.	Provide new grease trap.		2	\$ 8,000.00	\$ 16,000.00
P4	Mechanical SB104	Water service dose not have a water meter.	Provide water meter unless water is being metered in another location.		1	\$ 3,000.00	\$ 3,000.00

A/M/E/P Items Subtotals: \$ 26,110.00

**Approximate Total Cost** \$ 26,110.00